

# Product Change Notice

PCN Number: 2102

Part Number: TX/TV\_35 CHANGE IN TCXO ASIC

Customer: ALL

Customer Part Number: -----

Customer P.O. Number: -----

Originator: John D. Ivens

Date: 11 Mar. 2021

**Reason for Change:**

Current TCXO/VCTCXO ASIC has become obsolete. Raltron has implemented a new ASIC solution for TCXO's in this performance category.

**Description of Change:**

Raltron 5x3.2mm TCXO and VCTCXO with tight stability will have the obsolete TCXO/VCTCXO ASIC replaced with a new ASIC solution. Design and process will be optimized for this new ASIC.

**Comment(s):**

Change in ASIC will not effect the TCXO or VCTCXO Form, Fit, and Function. Mounting, Wire Bonding, Assembly, and Programming will be optimized for the new ASIC.

DATE OF CHANGE: 11 Mar. 2021

CUSTOMER NOTIFICATION REQUIRED:  Yes  No

CUSTOMER APPROVAL REQUIRED:  Yes  No

DATE OF CUSTOMER NOTIFICATION: 11 Mar. 2021

**Raltron Approval**

Engineering Sergio San Pedro

Date 11 Mar. 2021

Quality Assurance John D. Ivens

Date 11 Mar. 2021

**To Be Completed By Customer**

Accept Change  Change Not Approved  Requests Additional Information

Comments \_\_\_\_\_

Customer Signature \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

