

Product Change Notice

PCN Number: 2103

Part Number: TX/TV_57 CHANGE IN TCXO ASIC

Customer: ALL

Customer Part Number: -----

Customer P.O. Number: -----

Originator: John D. Ivens

Date: 11 Mar. 2021

Reason for Change:

Current TCXO/VCTCXO ASIC has become obsolete. Raltron has implemented a new ASIC solution for TCXO's in this performance category.

Description of Change:

Raltron 7x5mm TCXO and VCTCXO with tight stability with tight stability will have the obsolete TCXO/VCTCXO ASIC replaced with a new ASIC solution. Design and process will be optimized for this new ASIC.

Comment(s):

Change in ASIC will not effect the TCXO or VCTCXO Form, Fit, and Function. Mounting, Wire Bonding, Assembly, and Programming will be optimized for the new ASIC.

DATE OF CHANGE: 11 Mar. 2021

CUSTOMER NOTIFICATION REQUIRED: Yes No

CUSTOMER APPROVAL REQUIRED: Yes No

DATE OF CUSTOMER NOTIFICATION: 11 Mar. 2021

Raltron Approval

Engineering Sergio San Pedro

Date 11 Mar. 2021

Quality Assurance John D. Ivens

Date 11 Mar. 2021

To Be Completed By Customer

Accept Change Change Not Approved Requests Additional Information

Comments _____

Customer Signature _____ Title _____ Date _____

